Restringing Shade Category A

| resultinging strade cate                                    | gory A    |         |  |  |  |  |
|---|-----------|---------|--|--|--|--|
| Restring Shade  | UPC       | Price   |  |  |  |  |
| <br>Re-cording cellular shade w/2 cords                     | RC2A      | \$32.28 |  |  |  |  |
| <br>Re-cording cellular shade w/3 cords                     | RC3A      | \$36.90 |  |  |  |  |
| <br>Re-cording cellular shade w/4 cords                     | RC4A      | \$41.51 |  |  |  |  |
| Re-cording cellular shade w/5 cords                         | RC5A      | \$46.12 |  |  |  |  |
| <br>Re-cording cellular shade w/6 cords                     | RC6A      | \$60.00 |  |  |  |  |
| <br>Re-cording TDBU pleated shades add \$5.00               | TDBU      | \$7.00  |  |  |  |  |
| Installed new cord lock (Plus restringing)                  | SHDCLINS  | \$15.00 |  |  |  |  |
| Each additional cord  | RCAC      | \$5.00  |  |  |  |  |
| <br>Install new cord guide (Plus restringing)               | CRDGD/A   | \$4.00  |  |  |  |  |
| Restringing Blind Category B                                |           |         |  |  |  |  |
| Re-cording Blind w/2 cords                                  | RC2AVB    | \$36.90 |  |  |  |  |
| Re-cording Blind w/3 cords                                  | RC3AVB    | \$41.51 |  |  |  |  |
| Re-cording Blind w/4 cords                                  | RC4AVB    | \$46.12 |  |  |  |  |
| Re-cording Blind w/5 cords                                  | RC5AVB    | \$60.00 |  |  |  |  |
| Re-cording Blind w/6 cords                                  | RC6AVB    | \$70.00 |  |  |  |  |
| Re-cording Blind w/7 cords                                  | RC7AVB    | \$80.00 |  |  |  |  |
| Restringing loop ladder tape add per tape                   | RCLLT     | \$8.00  |  |  |  |  |
| Installed new cord lock (Plus restringing) (see price list) | INSTLCKA  | \$10.00 |  |  |  |  |
| Installed new cord lock (No restringing)                    | INSTLCKAN | \$22.50 |  |  |  |  |
| Install new cord guide (Plus restringing)                   | CRDGD/B   | \$22.50 |  |  |  |  |
| Install new drum (Plus restringing)                         | INSTLDRM  | \$8.00  |  |  |  |  |
| Installed new tilt gear A (see price list)                  | INSTLTGA  | \$10.00 |  |  |  |  |
| Installed new tilt gear B (see price list)                  | INSTLTGB  | \$15.00 |  |  |  |  |
| Replace ladder tape per tape (plus restringing costs)       | INSTLLDRT | \$22.50 |  |  |  |  |
| Shuffle slats or replace per ladder tape                    | INSTLTSLT | \$8.00  |  |  |  |  |
| Restringing Cord Loop Blind Category C                      |           |         |  |  |  |  |
| <br>Re-cording Blind w/2 cords                              | RC2ACL    | \$35.00 |  |  |  |  |
| Re-cording Blind w/3 cords                                  | RC3ACL    | \$45.00 |  |  |  |  |
| Re-cording Blind w/4 cords                                  | RC4ACL    | \$55.00 |  |  |  |  |
| Re-cording Blind w/5 cords                                  | RC5ACL    | \$65.00 |  |  |  |  |
| Re-cording Blind w/5 cords                                  | RC6ACL    | \$75.00 |  |  |  |  |
| Install new cord guide (Plus restringing)                   | CRDGDB/C  | \$5.00  |  |  |  |  |
| Replace cord loop clutch cover                              | RPCLCC    | \$6.00  |  |  |  |  |
| <br>Replace cord loop clutch A (see price list)             | RPCLCCA   | \$20.00 |  |  |  |  |
| Replace cord loop clutch B (see price list)                 | RPCLCCB   | \$30.00 |  |  |  |  |
|   |           |         |  |  |  |  |

| Replace cord loop clutch (see price list) C               | RPCLCCC         |          |            |  |  |  |  |
|---|-----------------|----------|------------|--|--|--|--|
| Replace cord loop in pleated shade under 6 feet           | RPCLU6          | \$18.45  |            |  |  |  |  |
| Replace cord loop in pleated shade over 6 feet            | RPCLO6          | \$23.06  |            |  |  |  |  |
| Hunter Douglas Ulraglide lift system Pull Cord Category H |                 |          |            |  |  |  |  |
| Re-cording Blind w/2 cords                                | RCHDLS2C        | \$40.00  |            |  |  |  |  |
| Re-cording Blind w/3 cords                                | RCHDLS3C        | \$50.00  |            |  |  |  |  |
| Re-cording Blind w/4cords                                 | RCHDLS4C        | \$60.00  |            |  |  |  |  |
| Re-cording Blind w/5cords                                 | RCHDLS5C        | \$70.00  |            |  |  |  |  |
| Re-cording TDBU pleated shades add \$15.00                | RCHDLSTD        | \$15.00  |            |  |  |  |  |
| HD ultraglide lift system Pull Cord Assembly A            | HDLSPCAA        | \$22.50  |            |  |  |  |  |
| HD ultraglide lift system Pull Cord Assembly B            | HDLSPCAB        | \$32.50  |            |  |  |  |  |
| HD PowerRise or Ultraguide shades Repair                  | HDPRUDR         | \$32.50  |            |  |  |  |  |
| Restring a Cordless Shade or Blind Category L             |                 |          |            |  |  |  |  |
| Re-cording Blind or Shade w/2 cords                       | RSCLS2C         | \$50.00  |            |  |  |  |  |
| Re-cording Blind or Shade w/3cords                        | RSCLS3C         | \$75.00  |            |  |  |  |  |
| Re-cording Blind or Shade w/4 cords                       | RSCLS4C         | \$100.00 |            |  |  |  |  |
| Replace cordless motors (see price list)                  | RPCLM           |          |            |  |  |  |  |
| Replace and transmission (see price list)                 | RPCLT           |          |            |  |  |  |  |
| Miscellaneous repair per cord                             | RDCLSPC         | \$22.50  |            |  |  |  |  |
| Day Night Shade Restring Category D                       |                 |          |            |  |  |  |  |
| Re-cording Blind or Shade w/2 cords                       | DNSRC2          | \$35.00  |            |  |  |  |  |
| Re-cording Blind or Shade w/3 cords                       | DNSRC3          | \$45.00  |            |  |  |  |  |
| Re-cording Blind or Shade w/4 cords                       | DNSRC4          | \$55.00  |            |  |  |  |  |
| Re-cording Blind or Shade w/5 cords                       | DNSRC5          | \$65.00  |            |  |  |  |  |
| Replace Cord Hold-down EA                                 | DNSHD           | \$3.00   |            |  |  |  |  |
| Replace tension spring                                    | DNSTS           | \$4.00   |            |  |  |  |  |
| Miscellaneous repair                                      | DNSMR           | \$17.50  |            |  |  |  |  |
| Replace end cap   | DNSEC           | \$3.00   |            |  |  |  |  |
| Restring in Shade or Blind F                              | lat Lift Tape ( | Category | <i>/</i> F |  |  |  |  |
| Ultra Glide (0.9 mm Cord or Flat Lift Tape) 2/cords       | RCFLT2          | \$40.00  |            |  |  |  |  |
| Ultra Glide (0.9 mm Cord or Flat Lift Tape) 3/cords       | RCFLT3          | \$48.00  |            |  |  |  |  |
| Ultra Glide (0.9 mm Cord or Flat Lift Tape) 4/cords       | RCFLT4          | \$56.00  |            |  |  |  |  |
| Ultra Glide (0.9 mm Cord or Flat Lift Tape) 5/cords       | RCFLT5          | \$72.00  |            |  |  |  |  |
| Ultra Glide (0.9 mm Cord or Flat Lift Tape) 6/cords       | RCFLT5          | \$88.00  |            |  |  |  |  |
| Ultra Glide flat lift tape cords spool                    | RCFLTCSP        | \$6.00   |            |  |  |  |  |
| Miscellaneous repair parts Category E                     |                 |          |            |  |  |  |  |
| Replace draw cord (Hunter Douglas tassels set)            | REPTSSHDS       | \$7.00   |            |  |  |  |  |
| Hunter Douglas tassels set                                | REPTSSHD        | \$4.00   |            |  |  |  |  |
|   |                 |          |            |  |  |  |  |

| Replace Tassels A                                    | REPTSSA       | \$1.00     |  |  |  |  |  |
|--|---------------|------------|--|--|--|--|--|
| Blind and Shade Repair Parts Category P              |               |            |  |  |  |  |  |
| Replace Tassels B                                    | REPTSSB       | \$1.25     |  |  |  |  |  |
| Replace Tassels C                                    | REPTSSC       | \$1.50     |  |  |  |  |  |
| Replace Tassels D                                    | REPTSSD       | \$1.75     |  |  |  |  |  |
| Replace Equalizers                                   | REPEQ         | \$1.00     |  |  |  |  |  |
| Replace End Cap A                                    | REPECA        | \$1.25     |  |  |  |  |  |
| Replace End Cap B                                    | REPECB        | \$1.75     |  |  |  |  |  |
| Tilt Wands A   | REPTWA        | \$12.00    |  |  |  |  |  |
| Tilt Wands B   | REPTWB        | \$17.00    |  |  |  |  |  |
| Tilt Wands HD  | REPTWHD       | \$20.00    |  |  |  |  |  |
| Tilt Wands Wood A                                    | REPTWWA       | \$15.00    |  |  |  |  |  |
| Tilt Wands Wood B                                    | REPTWWB       | \$20.00    |  |  |  |  |  |
| Replace stop ball A                                  | REPSTBA       | \$1.75     |  |  |  |  |  |
| Replace stop ball B                                  | REPSTBB       | \$2.25     |  |  |  |  |  |
| Valance A  | REPVALA       | \$1.25     |  |  |  |  |  |
| Valance B  | REPVALB       | \$1.50     |  |  |  |  |  |
| Valance C  | REPVALC       | \$1.75     |  |  |  |  |  |
| Valance C  | REPVALD       | \$2.00     |  |  |  |  |  |
| Valance SWF  | REPVALSWF     | \$4.00     |  |  |  |  |  |
| Cut Down Service or Shorter                          | nina Lenath ( | Category G |  |  |  |  |  |
| Cut down width of cellular/pleated shade (one side)  | CDWCS1S       | \$35.00    |  |  |  |  |  |
| Cut down additional side of cellular/pleated shade   | CDWCS2S       | \$27.50    |  |  |  |  |  |
| Cut down width of TDBU shapes (one side)             | CDWCSTP1S     | \$45.00    |  |  |  |  |  |
| Cut down width of TDBU shapes (additional side)      | CDWCSTP2S     | \$27.50    |  |  |  |  |  |
| Cut down width Mini Blind                            | CBWMB1S       | \$42.50    |  |  |  |  |  |
| Cut down width Venetian Blind                        | CBWVB1A       | \$36.90    |  |  |  |  |  |
| Cut down width 1" Wood Blind                         | CBWMBW1S      |            |  |  |  |  |  |
| Cut down width 2" Wood Blind                         | CBWMBW2S      |            |  |  |  |  |  |
| Shorten length of window covering (per ladder tape)  | SHRTNWC       | \$8.00     |  |  |  |  |  |
| Bottom Parts and Repair Category H                   |               |            |  |  |  |  |  |
| Replace Lift Cord Bottom Rail Stops Shade            | RPLCBP        | \$5.00     |  |  |  |  |  |
| Replace Lift Cord Bottom Rail Stops Shade (Fix Cord) | RPLCBPFC      | \$10.00    |  |  |  |  |  |
| Venetian Blind Cord Stops A                          | RPVBCSTPA     | \$5.00     |  |  |  |  |  |
| Venetian Blind Cord Stops B (Fix Cord)               | RPVBCSTPB     | \$10.00    |  |  |  |  |  |
| Bottom Rail Repair                                   | BRRP          | \$17.50    |  |  |  |  |  |
|  |               |            |  |  |  |  |  |